

Also see the General Safety and Health section and the following related safety and health topics pages:
Powered Industrial Trucks, Personal Protective ...

Occupational Safety and Health for Oil and Gas Well Drilling and Servicing Operations 1 Scope 1.1 Coverage
The purpose of this document is to recommend practices and procedures for ...

The IADC HSET Committee recently released the electronic IADC Drilling Rig Safety Inspection Checklist, which helps keep the operational integrity of rigs compliant. ...

Safety Alert From the International Association of Drilling Contractors The Corrective Actions stated in this alert are one company's attempts to address the incident, and do not necessarily ...

When the traveling block was lowered to the deck, the hammer union snagged the deadline and dragged a loop of drill -line down with it, effectively adding extra rope to the drill-line. When the ...

SAFETY ALERT Drill Rigs and Serious Injuries INCIDENT A number of serious drill rig injuries have recently occurred at underground mines resulting in fractures, amputation of fingers, ...

Historical BSEE Safety Alerts Safety Alerts are tools used by BSEE to inform the offshore oil and gas industry of the circumstances surrounding an incident or a near miss. ...

Safety Alert From the International Association of Drilling Contractors The Corrective Actions stated in this alert are one company's attempts to address the incident, and do not necessarily ...

Background information Geotechnical Engineering were using a Commacchio 305 drilling rig for borehole works. The incident occurred when the IP (injured person) was removing the drilling ...

Washington -- Operators of offshore oil and gas rigs and their contractors should establish and clearly communicate enhanced safety ...

A UDR 650 drill rig was being used when the driller stepped backwards and tripped over an overshot rod. He then fell to the ground and sustained a dislocated shoulder.

Partial overturn of rig During the routine daily maintenance of a BKJV drilling rig, the mast was being manoeuvred to facilitate the oiling of the chain when it became unstable. The offside ...

Working environments include both land and offshore operations. Differences in the working environments,



Safety alert drilling rig

personnel manning, equipment design and layout between the smallest land rig ...

Essential safety tips for drilling rig operators. Learn about pre-operation checks, equipment, emergencies, and NCCCO certification. Ensure safe operations with Marine ...

Alert 99 - 04 Rig Tong Snub Lines WHAT HAPPENED: During an inspection on a rig, the rig company found that the rig was using incorrect size wire rope lines for snub lines on ...

We welcome your ideas for future Safety Alerts. This material is presented for information purposes only. Managers & Supervisors should evaluate this information to ...

In the high-risk oil and gas industry, staying informed about potential hazards and emerging threats is paramount. Safety alerts for oil and gas play a crucial role, allowing for ...

Safety Alert is a tool used by BSEE to inform the offshore oil and gas industry of the circumstances surrounding a potential safety issue. It also contains recommendations that ...

Alert 23-01 - Drill string severed/parted while laying down drill pipe Alert 23-01 - Drill string severed/parted while laying down drill pipe WHAT HAPPENED: The drill crew was in the ...

Operators of offshore oil and gas rigs and their contractors should establish and clearly communicate enhanced safety measures in anticipation ...

A lack of training with hydraulic torque wrenches and a lack of understanding of the risks associated with the riser were among the major contributing factors that resulted in a ...

DrillSafe is a resource of safety information for the exploration industry. We aim to improve the standard of safety performance on drill sites through technical articles, hazard ...

Regular and periodic inspection and maintenance of the Crown Alert crown saver is necessary to keep your rig and crew safe. Crown Alert wants to remind all of ...

See drilling rig(s) rig blowout, 99 rig components, checking, 109 rig engine and generator, guards in place on, 74 rig floor moving pipe to, 82 rotary table and, 48 safety harnesses and, 45 slips ...

On rig floor at time of incident were: 3 employees, 2 third party employees, and 1 employee of the Drilling Contractor. The closest employee to the dropped CRT was the 3rd party tong operator ...

The Petroleum and Gas Inspectorate is concerned with dangerous objects dropping from drilling rigs. Dropped objects have included drill pipes, tubing, casing, elevators and even a three ...



Safety alert drilling rig

Web: <https://www.kwa-andries.co.za>