



Tornado hits drilling rig

Did a tornado hit a cactus 117 oil rig?

As per the Wikipedia article - "According to the National Weather Service, the tornado is believed to have peaked in intensity just after crossing I-40. There, the tornado struck the Cactus 117 oil drilling rig site at EF5 intensity, completely destroying it.

Does cactus drilling have a tornado rig?

Cactus Drilling has nearly 40 rigs operating in Oklahoma, a state that suffers an average of 52 tornadoes a year. In 2007, a tornado in the state blew away a trailer house, killing a company man and injuring another employee.

Did a tornado hit Pico Rivera?

A tornado ripped through a Pico Rivera neighborhood early Thursday morning, damaging homes, uprooting trees and toppling power lines. PICO RIVERA, Calif. (KABC) -- A tornado hit a Pico Rivera neighborhood early Thursday morning, the National Weather Service has confirmed.

Did Cactus rig 117 withstand an F5 tornado?

At a cost of approximately \$500,000, Cactus anchored its rig change houses to withstand an F5 tornado. On 24 May 2011, Cactus Rig 117, operating near Calumet, Okla., suffered a direct hit by an F5 tornado that resulted in an estimated \$14 million in damage. An F5 tornado damaged Cactus Rig 117 after hitting the site on 24 May 2011.

What happened at Cactus drilling?

In 2007, a tornado in the state blew away a trailer house, killing a company man and injuring another employee. Although neither worked for Cactus, the event gave Kathy Willingham, vice president of human resources and HSE for Cactus Drilling, the idea to prepare her company for tornado emergencies.

Is your drilling business prepared for an emergency?

In the drilling business, there's nothing like being prepared. Kenny Baker, drilling superintendent for Cactus Drilling Company, witnessed firsthand the value in having an emergency preparedness plan last year.

Serious Injuries Reported After Tornado Hits Texas Drilling Rig NBCNews A tornado touched down in northwestern Texas Wednesday, damaging a gas drilling rig and resulting in serious ...

Although many people had been skeptical about the usefulness and efficacy of anchoring the change house to create a tornado shelter, what happened during the 2011 ...

Famous drilling rig tornado photo In the drilling business, there's nothing like being prepared. Kenny Baker, drilling superintendent for Cactus Drilling ...



Tornado hits drilling rig

A tornado ripped through a Pico Rivera neighborhood early Thursday morning, damaging homes, uprooting trees and toppler power lines.

Crews on drilling rigs must expect tornadoes as a very real possibility, and Tony Maynard, H& P employee of 17 years and Rig Manager of over a decade, can give a firsthand account of a ...

As per the Wikipedia article - "According to the National Weather Service, the tornado is believed to have peaked in intensity just after crossing I-40. [15] There, the tornado struck the Cactus ...

The tornado hit two drilling rigs. An employee of the first drilling rig that was hit was residing in a single-wide mobile home that was anchored into the ground.

(Reuters) - At least three people were injured on Wednesday when a tornado hit a natural gas drilling rig in northern Texas, the Hemphill County sheriff and a hospital official ...

(Reuters) - At least three people were injured on Wednesday when a tornado hit a natural gas drilling rig in northern Texas, the Hemphill County sheriff and a hospital official said.

At least three were injured after a tornado hit a natural gas drilling rig in northern Texas on Wednesday evening. At around 5:20 p.m. local time, the tornad...

The issue was the context; to put it bluntly, this was among the most violent tornadoes ever seen in modern times. The feats were numerous, ...

At a cost of approximately \$500,000, Cactus anchored its rig change houses to withstand an F5 tornado. On 24 May 2011, Cactus Rig 117, ...

The storm destroyed a drilling rig being operated nearby by Denver-based Cimarex Energy Co. Devon officials are assessing the damage to the \$140 million plant, but ...

Although many people had been skeptical about the usefulness and efficacy of anchoring the change house to create a tornado shelter, what ...

A tornado hit a gas drilling rig in the northern part of the U.S. state of Texas on Wednesday, reportedly leaving three workers injured.

TORO DRILLING offers as first instance the method of Diamond Drilling, and its subsidiary TORNADO DRILLING provides services in both systems, Diamond Drilling and Reverse ...

Floyd said he didn't know the extent of the workers' injuries at the rig owned by Cactus Drilling. Emergency workers also contained a gas leak caused by damage to the plant, and damage ...



Tornado hits drilling rig

When it hit, the rig's pipes and drill head were inserted deep in the well's borehole, which provided the drilling pipe with 200000lb of downforce. Despite this, and despite the fact ...

When it hit, the rig's pipes and drill head were inserted deep in the well's borehole, which provided the drilling pipe with 200,000lb (91,000kg) of downforce. [11]: 6 Despite this, and despite the ...

At least three people were injured on Wednesday when a tornado hit a natural gas drilling rig in northern Texas, the Hemphill County sheriff and a hospital official said.

It didn't hit the plant, but it did hit the Cactus 117 rig, which was drilling a gas well. No one was hurt as the rig crew and Devon employee's at the gas plant all were able to get ...

veral minutes. When the tornado crossed Interstate 40, maximum radial velocities were just o a range of about 10 km and height of approximately 170 m. Interstate 40. The rig reportedly ...

24/7/365 Through long nights, weekends, holidays and almost all types of weather, drilling is taking place. A mom and a rig manager - an unlikely pair, ...

When it hit, the rig's pipes and drill head were inserted deep in the well's borehole, which provided the drilling pipe with 200,000 lb (91,000 kg) of downforce. [75]: 6 Despite this, and despite the ...

Crews on drilling rigs must expect tornadoes as a very real possibility, and Tony Maynard, H& P employee of 17 years and Rig Manager of over a decade, can ...



Tornado hits drilling rig