

On an oil rig, the Derrickman is the man responsible of handling drill pipes on the derrick, he always is a clever man who do a very critical job. sometimes unexpected accident may happen ...

All 55 employees in the mine at the time of the accident were able to escape thanks to well-planned and rehearsed evacuation drills, while the crew of the drilling rig fled the platform ...

Rig explosions, fires, capsizing/sinking, oil spills, and the loss of workers and marine lives have been the most catastrophic forms of offshore oil and gas drilling disasters in ...

Oil and gas industry accidents have left indelible marks on history, causing immense human loss, environmental devastation, and financial damage.

A 42-year-old rig, Rig 110, collapsed off the coast of Trinidad on Sunday morning leaving one worker missing and another injured. The incident occurred at about 3:00 a.m. ...

Al-Masry Al-Youm has obtained exclusive photos documenting the moment a marine drilling rig, owned by ADES Holding, capsized on Tuesday ...

OKLAHOMA CITY (AP) -- Ten workers have died over the past decade at well sites linked to drilling contractor Patterson-UTI, the same driller involved in this week's rig ...

Within seconds, a massive geyser of molten lava shot over 150 feet into the air, instantly melting the drilling rig and igniting nearby structures.

The 5 Major Offshore Oil Rig Disasters Drilling for oil is an incredibly dangerous job, with more than 1,500 men and women killed on oil rigs between 2008 and 2017 alone. ...

7 Common Accidents: 1. Fire and Explosions This is the leading accident in the oil drilling industry. In the process of drilling, blowouts, tripping out and swabbing, combustible gasses ...

The ISP also provides for recognition of drilling rigs that achieve the accomplishment of operation for a one-year period without a recordable incident or illness, ...

News Calamity at sea: Missing man's family in pain after rig collapses Newsday Reporter Monday 23 December 2024 The damaged Rig 110, owned and operated by Well ...

While action has been taken to minimise the risks of accidents on offshore installations and improve the safety

Accident on drilling rig

An offshore incident last week resulted in a rig crewmember passing away onboard the Noble Viking drillship. Jefften Peter was a Control Union contractor who was onboard the ...

The ISP also provides for recognition of drilling rigs that achieve the accomplishment of operation for a one-year period without a recordable ...

News Calamity at sea: Missing man's family in pain after rig collapses Newsday Reporter Monday 23 December 2024 The damaged Rig ...

Authorities Investigating Oklahoma Rig Explosion, Deadliest U.S. Drilling Accident In Years Federal and state authorities are investigating the cause of the ...

The drilling contractor, in this case Patterson-UTI Drilling Company, LLC (Patterson-UTI), brings the infrastructure (drilling rig) and supplies the workforce (rig crew) ...

Pre-explosion risks and precautions Deepwater Horizon drilling rig before the explosion In February 2009, BP filed a 52-page exploration and environmental impact plan for the Macondo ...

The Deepwater Horizon disaster is among the most infamous oil and gas industry accidents. The offshore drilling rig exploded due to a ...

(Fiction, though in reality there are concerns that something like this could happen) Yellowstone Drilling Accident Unleashes 150-Foot Lava Geyser Casper Planet -- April 27, 2025 ...

Alexander L. Kielland was a Norwegian semi-submersible drilling rig that, on 27 March 1980, capsized in the Ekofisk oil field in the North Sea, killing 123 ...

Alexander L. Kielland, an accommodation rig being attached to a drilling platform, capsized on 27th March 1980 on the Ekofisk field in the North Sea. During stormy weather, one of the five ...

Philadelphia officials and engineering firm Langan have confirmed that a company project manager and geotechnical engineer died July 6 in a ...

Construction worker dies in "tragic" accident A drilling rig fell on top of a 55-year-old man at a construction site in Philadelphia on Tuesday night.

7 Common Accidents: 1. Fire and Explosions This is the leading accident in the oil drilling industry. In the process of drilling, blowouts, tripping out and swabbing, ...



Accident on drilling rig

Abstract: At 1:30 a.m. on April 13, 2021, an employee was working 30 feet below ground on a Precision Drilling Rig floor running intermediate casing into the well by connecting each length ...

Web: <https://www.kwa-andries.co.za>