



Drilling rig hit by tornado in oklahoma

Despite not being an official damage indicator on the Enhanced Fujita scale, the National Weather Service Norman, Oklahoma rated the damage to the Cactus ...

On May 24, 2011, a Cactus Drilling rig near El Reno was directly hit by an EF5 tornado. All of its workers ran to a portable building used for changing clothes and escaped ...

Atlas Drilling, LLC is an independent oil and gas drilling contractor based in Woodward, Oklahoma. We currently operate 10 drilling rigs in the Mid ...

Crews on drilling rigs must expect tornadoes as a very real possibility, and Tony Maynard, H& P employee of 17 years and Rig Manager of over a decade, can give a firsthand account of a ...

A tornado left damage and injuries after it hit a gas drilling rig in the Texas panhandle Wednesday night. Hemphill County Sheriff's Office confirmed the tornado touched ...

Jul 20, 2021 - Forwarded from one of our service techs: This happened yesterday, 5/24/2011, close to Calumet, OK- Pictures were taken by an SLB employee who was there - An F5 ...

Oklahoma City-based Cactus Drilling Co. LLC credits its reinforced safe room for helping 13 employees and contractors survive a direct ...

At least three were injured after a tornado hit a natural gas drilling rig in northern Texas on Wednesday evening. At around 5:20 p.m. local time, the tornad...

Rig Fleet Our high-spec, fit-for-purpose rigs are equipped with the technology, capacities and capabilities required to tackle today's most complex drilling ...

This past May Oklahoma was hit by a string of tornadoes during a six day period, creating life-threatening conditions compounded by major flooding.

The 2011 El Reno-Piedmont tornado was a long-tracked, deadly and extremely powerful EF5 tornado that struck central Oklahoma on the evening of May 24, 2011. The ...

Yep at our safety meeting 3 days ago they showed us pics of a rig that got hit by a tornado in Oklahoma where everyone was in the tool room that was anchored down...some of ...

Crews on drilling rigs must expect tornadoes as a very real possibility, and Tony Maynard, H& P employee of



Drilling rig hit by tornado in oklahoma

17 years and Rig Manager of over a decade, can ...

The major tornado alley in the U.S. extends from the Dakotas south to Texas (Figure 1) and crosses several major oil/gas producing basins. Recently, there have been incidents of ...

Cactus Drilling ultimately spent around \$500,000 to anchor its rig change houses to withstand an F5 tornado. In 2011, a Cactus rig in Oklahoma ...

EL RENO -- An El Reno official says 20 workers at an oil and gas rig were hurt when a possible tornado moved through the area. Community Services Director Terry Floyd also said Tuesday ...

When it hit, the rig's pipes and drill head were inserted deep in the well's borehole, which provided the drilling pipe with 200,000lb (91,000kg) of downforce. [11]: 6 Despite this, and despite the ...

INTRODUCTION On 24 May 2011 a total of 22 tornadoes struck central Oklahoma (Fig. 1). Fortunately, these tornadoes missed towns and metropolitan areas. The next day, the ...

The big tornado in the movie hit the town of El Reno which is west of Oklahoma City a half hour or so. It turns out that El Reno was close to a real tornado (the El Reno-Piedmont ...

AboutPressCopyrightContact usCreatorsAdvertiseDevelopersTermsPrivacyPolicy & SafetyHow worksTest new featuresNFL Sunday Ticket© 2025 Google LLC

The El Reno tornado (B2; Fig. 1) struck a very interesting structure: a 1.9 million lb natural gas drilling derrick and rig with over 200,000 lbs of down force on the drilling pipe (Fig. 9).

A BOE contributor sent pictures of Cactus Rig 117, which was destroyed by a tornado on May 24, 2011, near Calumet, Oklahoma. The F5 ...

Today, the contractor has 35 Rocket Rigs in its fleet. In 2010, Mr Baker was promoted to drilling superintendent, fulfilling the goal he'd set for ...



Drilling rig hit by tornado in oklahoma

Web: <https://www.kwa-andries.co.za>