



Ok drilling rig fire

OKLAHOMA CITY -- The remains of five gas rig workers missing since a fiery explosion in eastern Oklahoma have been recovered, authorities said Tuesday.

OKLAHOMA CITY (AP) -- The failure of safety devices designed to prevent blowouts contributed to an explosion and fire that killed five workers ...

A failure of two preventive barriers in place to stop a blowout were the main causes of a blowout and rig fire that killed five workers at the Pryor Trust gas well in Pittsburg County, ...

A Pittsburg County, Okla., jury has found National Oilwell Varco, a Houston-based company partially responsible for the 2018 explosion and fire that killed five men.

OKLAHOMA CITY (AP) -- The failure of safety devices designed to prevent blowouts contributed to an explosion and fire that killed five workers last year at a ...

QUINTON, Okla. - Attorneys for the family of a man killed in a drilling rig explosion say the operator of the oil well was trying to save money ...

Patterson-UTI Energy Inc.'s Rig 219 was damaged in a 2018 fire near Quinton, Okla., that killed five men. Well operator Red Mountain Energy ...

Drilling contractor Patterson-UTI said some of its employees were missing on Monday after a fire at one of its drilling rigs in Pittsburg County, Oklahoma.

The bodies of five workers, including one Texan, were recovered Tuesday after an explosion ripped through a drilling rig in Oklahoma, triggering what appears to be the nation's ...

Last January, five oil workers were killed in a fire and explosion at a Quinton, Oklahoma drilling rig. This was the deadliest drilling accident in the U.S. since 2010, when 11 ...

Two years ago, an oil well near a small Oklahoma town exploded into a fireball that swept through a drilling rig, killing five in an accident ...

An oil rig site exploded in El Reno Friday night, authorities confirm. El Reno Police said it happened around 9 p.m. at the site near Airport Road ...

The report identifies a lack of regulations governing onshore drilling safety as well as shortcomings in safety



Ok drilling rig fire

management systems and industry ...

Smoke billows from the site of a gas well fire near Quinton, Okla., early Monday, Jan. 22, 2018. Several people are missing after a fiery ...

An accident that killed five workers at an Oklahoma drilling site earlier this year may have started after natural gas escaped from the well and safety equipment failed to ...

The driller involved in the deadly Oklahoma rig explosion has a history of fatal accidents by Sean Murphy, Associated Press, January 25, ...

Oklahoma City, Oklahoma, August 16, 2018: Today the U.S. Chemical Safety Board (CSB) released a factual update into its ongoing investigation of the ...

The fire is out after an explosion ripped through an eastern Oklahoma natural gas drilling rig. Five people are missing after the blast that sent plumes of black smoke into the air ...

An ongoing federal investigation shows there were warning signs that natural gas was flowing into a well getting drilled in eastern Oklahoma ...

Several people are missing after an explosion ripped through an Oklahoma drilling rig Monday. CBS News correspondent DeMarco Morgan has the latest bscribe ...

Regulators say the blowout that killed five workers on a Patterson-UTI rig in Oklahoma was the product of a slow-moving series of missed signals, misleading testing, and ...

A drilling rig blowout and 7 h fire that killed five workers who were trapped in the rig's small cabin were the result of a string of management and operator failures at an ...

June 12, 2019, Oklahoma City, OK - Today, the US Chemical Safety Board released its final investigation report into the blowout that fatally injured five workers at the Pryor Trust gas well ...

An accident that killed five workers at an Oklahoma drilling site earlier this year may have started after natural gas escaped from the well and ...

Blowout in Oklahoma Wednesday, Oct 30 2019 A training video for the onshore drilling industry detailing lessons learned from the January 22, 2018, blowout and fire at the ...

2D animation shows what led to a large explosion that fatally injured five workers during drilling operations at a gas well in Pittsburg County, Oklahoma.



Ok drilling rig fire

A local emergency manager says crews are allowing a fire to burn out following an explosion at a drilling rig in eastern Oklahoma to avoid spreading contaminants.

OKLAHOMA CITY (AP) -- Ten workers have died over the past decade at well sites linked to drilling contractor Patterson-UTI, the same driller involved in this week's rig ...

QUINTON, Okla. (AP) -- Five people are missing after a fiery explosion ripped through an eastern Oklahoma drilling rig on Monday, sending plumes of black smoke into the ...

Accident Occurred On: 01/22/2018 | Final Report Released On: 06/12/2019 Accident Type: Explosion and Fire Investigation Status: The CSB's final report was released at a news ...

Web: <https://www.kwa-andries.co.za>