



Surface drilling rig accidents

Drilling accident investigation - Drilling at Borehole 4 Drilling at Borehole 3 was completed on 7 August 2012 at which time Silver City Drilling moved the drill rig to the Borehole 4 location. As ...

Rig explosions, fires, capsizing/sinking, oil spills, and the loss of workers and marine lives have been the most catastrophic forms of offshore oil and gas drilling disasters in ...

History's worst oil rig explosions, spills, and accidents. Get the facts on everything from the 1988 Piper Alpha explosion to the 2010 Deepwater Horizon tragedy.

The Deepwater Horizon rig was drilling an oil well in the Macondo prospect that was intended to be plugged with cement and then completed ...

Regulators and the energy industry need to close regulatory gaps that contributed to one of the worst oil drilling accidents in decades, a federal ...

Drilling accident investigation - Drilling at Borehole 4 Drilling at Borehole 3 was completed on 7 August 2012 at which time Silver City Drilling moved the drill ...

Since these numbers are so severe, TriTech Safety has made it a priority to publish this article on the most common accidents in the oil and gas well ...

5 days ago; MSHA investigates each mining fatality and prepares the following documents to alert the mining community and prevent similar occurrences. ...

A drilling contractor has died at a remote mineral exploration site in Western Australia. The 29-year-old man is the second fatality in WA's resources sector this year after a ...

Sea Gem was Britain's first offshore drilling platform which capsized on 27 December 1965 while lowering the rig onto the surface of the water. It is believed that, the rig fell sideways due to ...

They were attempting to complete a natural gas well that had been drilled, cased, and perforated when wellhead control was lost because of mechanical problems both down the well bore and ...

The drilling crew had drilled about 1,900 feet, when the drill bit became bound, preventing both further drilling and drill pipe extraction. The well sat idle in the bound-up condition for about ...

In 1983, the worst-ever diving accident occurred. Five people working on an oil rig experienced explosive



Surface drilling rig accidents

decompression, which caused them to die in horrific ways.

3 days ago In drilling operations, faults, as a common structural geological phenomenon formed by tectonic movements within the Earth, pose many challenges to drilling work. As a ...

Advancements in Drilling Equipment Continuous advancements in drilling equipment, such as more powerful and efficient drill rigs, are transforming ...

Overview Alaska Arkansas California Colorado Delaware Illinois Indiana This list is complementary to the List of pipeline accidents in the United States. Large accidents, qualifying as industrial disasters are included. The production process encompasses all parts of the process from drilling for fuels to refining or processing to the final product. It also includes storage and disposal of waste. Unless otherwise stated, all accidents are associated with p...

The major accidents at the oil and gas rigs are related to pressure underbalance and kick or blowout while performing drilling operations. So, there are some safety barriers ...

design a supporting surface for the drill rig in accordance with good engineering practice to adequately support the drill rig during all drilling and drill rig set-up activities;

Failures during the drilling and exploitation of hydrocarbons that result in catastrophic offshore oil and gas accidents are relatively rare but if they occur the ...

The 2018 explosion and fire outside Quinton, Okla., killed five people, making it the deadliest accident in the drilling industry since 2010, ...

Discover the incredible true story of Lake Peigneur, where a drilling accident caused the lake to drain--and swallow a rig, barges, and trees.

Surface drilling rigs play a crucial role in industries like mining, construction, and oil & gas exploration. These versatile machines are ...

All 55 employees in the mine at the time of the accident were able to escape thanks to well-planned and rehearsed evacuation drills, or through heroic efforts by co-workers. The ...

A drilling contractor has died at a remote mineral exploration site in Western Australia. The 29-year-old man is the second fatality in WA's ...

Drilling rigs can be dangerous, and having a job on a drilling rig can put one in harm's way. Here are the leading causes of drilling rig disasters.



Surface drilling rig accidents

7 Common Accidents: 1. Fire and Explosions This is the leading accident in the oil drilling industry. In the process of drilling, blowouts, tripping out and swabbing, ...

On 5 November 1983, four divers and a crew of workers were engaged in routine maintenance on the Byford Dolphin, a semi-submersible drilling rig in the North Sea. Two divers were inside a ...

Web: <https://www.kwa-andries.co.za>